

Ship's name "CENTRAL CO"

Port GAL.

No. 7999

Class is subject to

1st Last survey date 1.4.65.

- 1 Forward scavenging blower rotor being dealt with as necessary by 5.65.
- 2 M/E. NO 5 cylinder cover being specially examined by 5.65 (6 mos limit)

ABS. dec 2.65 commenced 2.64 not advanced.

Examined NO 5 M/E. Turbo Superchargers due to excessive wear on after bearing of the Rotor shaft.

It is recommended that - M/E. NO 5 Turbo-Superchargers Rotor shaft + after bearing being specially examined and dealt with as found necessary on vessel's arrival at Buenos Aires at end of present voyage.

It is submitted that this vessel is eligible to remain as **CLASSED**.

with fresh record of

ABS. 2.64 on completion of survey
Subject as above & as now recommended.

To Complete 17BS

E.G. Boiler Safety Valves to adjust under steam.

La. Bas. 25
for La. Macon

© 1921
17. 5. 65
Lloyd's Register
Foundation