

Received from Chief Ship Surveyor.....21 JUL 1967

SHIP'S NAME "CUTRAL CO" REPORT B.As. No. 33811

Outstanding Conditions of Class: SUBJECT to 30 fathoms of chain cable  
(bent links failed 7,61) being annealed and proof tested at the  
earliest opportunity.

S.R.L. Appendix. (As before ~~or None~~)

Nature of Present Survey: (Afloat ~~and in drydock~~)

Contact damage repairs.

Recommendation:

SUBJECT as above.

As Now. Subject

IN S.R.L. APPENDIX.

(Main structure partly of P.5 Steel).  
(Rudder stock twisted 16° (9,61))



© 2021  
R.S.G.

11/7/67  
Lloyd's Register  
Foundation

012711-012715-0212