

26th June, 1962.

BUENOS AIRES.

"CUTRAL CO" As the result of a survey held at Rio on the 31st May, the class of this ship has been continued subject, inter alia, to the windlass being examined under working conditions at the earliest opportunity. Please inform the Owners accordingly.

At the same time I shall be glad if you will remind the Owners that thirty fathoms of chain cable (bent links faired 7.61) require to be annealed and proof tested at the earliest opportunity.



© 2021

Lloyd's Register  
Foundation

012711-012715-0223