

16. MAY 1966

Ship's Name SS/~~XX~~ 'BONNA'

Gross tons 6910 Port of Registry Panama Port Colombo

Date of build 6-1944 Is there a Rpt. 9? No Rpt. No. 6069

No. of visits Three First date 2.3.66 Last date 8.3.66

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) - KOB 14746

Date of completing rpt. 2.4.66 Surveyed at, if different from Port above -

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -

Has a Load Line Survey been held? No Summer freeboard as verified -

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) None

Survey fees Rs 180.00 Damage fee - Expenses Rs 27.00 S.A. fee Rs 100.00

I have surveyed the above-named ship in accordance with the Rules for commencement of a General Examination for postponement of the Special Survey.

Please see London letter to Owners SEI/DET, 18th February, 1966, and cables to Colombo.

Now Examined for General Examination

Fore Peak tank internally.

Repairs

Fore peak tank suction valve overhauled and extended spindle put into working order.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed ~~was~~/without fresh record of ~~exceeding~~ Survey, subject to any conditions of class at present outstanding being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

MONDAY 13 JUN 1966 (B. Borkett)

Deferred for SS

Surveyor to Lloyd's Register of Shipping

FOR CHAIRMAN CLASS. CITEE

012122-012727-0217

ALSO FOR... RECORDS DEPT. POSTING HEADER CERT

16 MAY 1966

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

Cable SWH - of GE check