

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name ~~"WATERINA"~~ **BONNA** Official No. ~~175392~~

Port of Registry ~~Wellington, N.Z.~~ **Panama**

This ship has been under survey at **VANCOUVER, B.C.**


on **7th to 9th March,** **1956** and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~—

2-17" dia. ventilators coamings 36" x 43" fitted to upper deck for air supply to No.1 Lower Hold. Fitted with wood plugs and canvas covers.

[Signature]
SURVEYOR TO LLOYD'S REGISTER.

14th March, 1956.

[Handwritten signature]



A copy of this Report has been placed on board.



RECEIVED
MAR 17 1956
MONTREAL



© 2021

Lloyd's Register
Foundation