

Messrs. Cheoy Lee Shipyard, Hong Kong.

Yard No. 652.

Sister ship "KYUNG NAM"

Chief Ship Surveyor

Received from Chief Ship Surveyor

AME m.s. "SILVER DRAGON"

REPORT

H.Kg. No. 13532.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

L. 189'-3"

D.33'-0"

D.17'-0"

The equipment of anchors and cables has been supplied in error in accordance with letter "k" instead of letter "l" Table 53 of the Rules. To compensate for the loss in weight IT IS SUBMITTED an additional length of chain cable be supplied and the Surveyors advised accordingly.

The scantlings and arrangements, as reported, conform with the Society's Revised Rules and Regulations, and are in accordance with or equivalent to those shown on the approved plans.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

100A1 DS 3,57.

SUBJECT to 15 fathoms of chain cable being supplied at the earliest opportunity.

*of proper size wt. & test*

1 dk; pt E.W.  
DBf 112t; FPT 110t; APT 40t.  
4BH; LACP  
P.47' F.21'  
Mchy Aft.  
O.L. 206'-2"  
Extreme breadth 33'-9"  
Rise of floor 3"  
ESD  
(1) 1.5/16"



SUBJECT

NOTE: The endorsement of this case has been deferred for discussion with Mr. Anderson in this Office.

*R.S.F.*  
30.7.57  
20/8/57

© 2021

Lloyd's Register Foundation

*See SO. 111  
D.T.*

8410-15610-442710 012744-012751-0148