

15 JUL 1965

Ship's name "RICARDO MANUEL"

Port LIS

No. 11026

Class is subject to NIL

Last survey date 18.2.65.

S.R.L. - Appendix ~~None~~ - NIL

Docking Wear down 0.7 in

TS due 5/65, now held

C.S. 17 advanced.

Screw shaft found corroded in way of stern bunk. As no spare shaft available, the shaft machined to remove pitting and the Surveyor recommends the screw shaft be renewed by 2/66 (12 months).

It is submitted that this vessel is eligible to remain as **CLASSED**, on the

record TS (C.S.) 2/65 withheld.

Subject as recommended.

Lu
14/7/65

Items not seen for more than ^{six and a} ~~seven~~ years:-

all m/c journals and main bearings. m/c Fuel injection pumps.

Engine tested working and manoeuvring

Started aft operating engine.

Items last seen 5/61 and now due for survey

Holding down bolts and chocks.

Ballast pump. C.S. pump.

Lub. oil cooler

Pumping arrangements

Separate oil fuel tanks

Steering machinery

Windlars

Both air receivers

Other listed equipment

© 2021
19/7

Lloyd's Register
Foundation

012779-012785-0164