

012792-012795-0055

2m, 10, 30.

4 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Courage I

Rpt.

hwe 99879
Mch 10595

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

Mine explosion

Main and Auxiliary engines & 6 sea valve closed broken
all renewed.

+Lure 10:41 / 18:41 +NE 10:41

Delete by in particulars & markers same. & NHTP.

Insert particulars as per Mch 10595.

It is concluded that the thrust shaft has renewed, that all pumps were
examined & that the spare gear is in order.

A report on the Electrical equipment is required.

See book
2/10/41

24/11/41