

COPY

LLOYD'S REGISTER OF SHIPPING

3587



Port Aden.

Date 30th August, 1963

This is to Certify *that I have*
surveyed the **/T "SIR BERNARD REILLY" 261 Gross tons of Aden**
on account of repairs to the starboard side shell and bulwark
plating

and that I am transmitting to the Committee of Lloyd's Register of
Shipping, London, a report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I am
recommending that she be **continued as classed without restriction**
regarding the starboard side shell plating i.e. sheer, first
below No.5 from forward and adjacent bulwark.

P. H. Ferri

P.H. Ferri.

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 80m,4,62 (MADE AND PRINTED IN ENGLAND.)

012827-012835-0161