

COPY

# LLOYD'S REGISTER OF SHIPPING

3581



Port Aden

Date 17th August, 1963.

**This is to Certify that I have**

*surveyed the* s.t. "SIR BERNARD REILLY" *Gross tons* 261 *whilst*  
on Messrs. A. Besse's floating dock at this port on the  
15th August, 1963 for Docking and AFS.

*and that I am transmitting to the Committee of Lloyd's Register of*  
*Shipping, London, a report, stating that all repairs recommended by*  
*me have been completed to my satisfaction, also that I am*  
*recommending that she be* retained as classed with fresh record  
of DS 8,63 subject to as now recommended the starboard side  
shell plating sheer & 1st. below No.5 from forward (indented)  
and adjacent bulwark being specially examined and dealt with as  
necessary at the next Special Survey.

*P. H. Ferri*

P. H. Ferri.

Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

AS Annual Survey  
BiS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 80m,4,62 (MADE AND PRINTED IN ENGLAND.)

012827-012835-0171