

Port Engineer's  
Department.

OFFICE NOTES.

To,  
The Port Engineer,  
Aden.

Aden, 26th April, 1949.

S.T. SIR BERNARD REILLY.

The list of requirements by the B.C. Surveyor does not include the annual requirements, the list is in addition to the annual requirement.

We should get to know what they want with the Main Engines and Auxiliaries as well as the the boiler and propeller shafting, etc.

If this is forthcoming we will have enough information to arrange our docking work, etc., and so get the Tug back on duty as fast as we can.

Sd/- J.B. HALTON

WORKSHO SUPERINTENDENT, ADEN.



Lloyd's Register  
Foundation

012827-012835-0176