

COPY,

Port Trust Workshop  
Aden 14-4-49


From,  
The Workshop Superintendent  
Ad en Port Trust

To, Port Engineer Aden

Subject. S,T. Sir Bernard Ralley

I have asked about this previously but nothing seems to have been done. We will have enough repairs next drydocking to warrant staying on Dock for 3 to 4 days and I suggest that we do the Special Survey then staying on the dock for that purpose. There has never been a surveyor on board, except the Govt Boiler inspector since we bought the tug, you will note that the yearly inspection is overdue. We bought the tug in 1946.

Sd/- J.B. Halton  
workshop Superintendent.



Lloyd's Register  
Foundation

017827-017835-0180