

7th September, 1962.

MESTRE.

0731 "LUCERNA" - As recommended, except that as it is normal practice to make at least two examinations of Metalock repairs before regarding them as permanent the class has been continued subject also to the after air compressor water jacket (Metalocked 4.62) being examined by the end of February, 1963.

In the circumstances an amended interim certificate should be issued.

012827-012835-0286