

LLOYD'S REGISTER OF SHIPPING

FOUNDED 1780

RE-CONSTITUTED 1834

LLOYD'S MACHINERY CERTIFICATE
(LMC)

This is to Certify that the Machinery of the

Steam Tanker "MARIAROSA AUGUSTA"

23108 Tons, of Palermo

has been Specially Surveyed by the Surveyors to this Society during
construction at Trieste

and was reported to be on the 15th April, 1958
in good working condition.

The Record \times LMC has been made in the Register Book, subject
to Periodical Surveys as required by the Rules.

PARTICULARS

| | | | |
|--|--|---------------------------------------|-------------------------------|
| Description of Machinery | 2 steam turbines with D.R.gearing to screwshaft 2 Water Tube Boilers | | |
| Makers of Main Engines | Cantieri Riuniti Dell'Adriatico | | |
| Makers of Main Boilers | Cantieri Riuniti Dell'Adriatico & Babcock & Wilcox Ltd. | | |
| Approved pressure of Main Boilers | 968 | lb. per square inch saturated steam | |
| | 900 | lb. per square inch superheated steam | |
| Steam Temperature | 860°F | | |
| Approved pressure of Aux./Donkey Boilers | — | lb. per square inch | |
| Approved pressure of Steam Heated Steam Generators | — | lb. per square inch | |
| Approved total | B.H.P. S.H.P. | 17600 | at 103 r.p.m. of Propeller |
| The main engine is not to be operated continuously between 47 & 53 R.P.M. | | | |

Witness my hand

W. J. Ferguson
Secretary

Chairman


71, Fenchurch Street, London, E.C.3. 1st July, 1958.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and
which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

HH-

3



© 2021

Lloyd's Register
Foundation

012852 - 012860 - 01261