



# LLOYD'S REGISTER OF SHIPPING

Via Mazzini No. 9, Trieste

3rd July, 1958

Telefono: 24420

Indirizzo Telegrafico: Register, Trieste

- 5 JUL 1958

Ans'd .....

Reference  
ssn(S)

Dear Sir,

"MARIAROSA AUGUSTA"  
Trieste First Entry Report N°. 14790  
Machinery Report 4a.

With reference to your letter dated 1st instant the contents of Paragraph 1 on page 2 are not understood.

You state that the diameters of the wheel shafts have been reported as '2M' and '4M' and this would appear to be incorrect.

From our records here we reported the wheel shaft diameters as follows :-

Wheel Shafts: diameters at bearings

|      |          |
|------|----------|
| 1st  | 304.6 mm |
| Main | 609.4 mm |

These figures have been checked and are correct and we would be pleased to receive further information regarding the symbols '2M' and '4M' as we cannot trace any reference to these in our report.

We note, however, that the pinion shaft diameter was reported as follows :-

Pinion Shafts: diameter at bearings

|          |     |             |
|----------|-----|-------------|
| External | 1st | ( 177.75 mm |
| Internal | 1st | ( 63 mm     |

The figure 177.75 is a typographical error and should read 177.57 mm. Please amend our report 4a accordingly.

Regarding Paragraph 2 we have to confirm that this vessel is NOT fitted with a steam heated steam generator.

Yours faithfully

The Secretary  
L o n d o n



*J. J. Wilson*  
For the Surveyors.

Lloyd's Register  
Foundation

012853-012860-0279



CLASSIFICATION

C # *DM*

*With a further from 2. The  
diameters of the wheels is refuted as  
in way of the wheels. This which appears to be diameter of wheel  
25 1/2 inches & 50 inches  
diameters are required*

STEEL & CO. LONDON  
SHEET, PLATE, ETC.  
BATH JUL 2 -

LODGE'S REGISTER OF SHIPPING



© 2021  
Lloyd's Register  
Foundation

