

# LLOYD'S REGISTER OF SHIPPING

FOUNDED 1760


RE-CONSTITUTED 1834

## Certificate of Class

Steam Tanker "ESSO DUBLIN"  
Official Number 301088 Port of Registry London  
Owners Esso Petroleum Co. Ltd.,  
Builders, and where and when built Cantieri Riuniti Dell'Adriatico. Monfalcone, May, 1960

REGISTERED TONNAGES  
Gross 23719.70  
Net 12751.59

MOULDED DIMENSIONS  
Length 660' 0"  
Breadth 90' 0"  
Depth 47' 0"


This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 14th May, 1960 in a fit and efficient condition and in accordance with the Rules; also that she has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character  100A1 Oil Tanker

subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

Tropical	10	feet	11½	inches (T).	Winter	{	12	feet	11¼	inches (WNA).
Summer	11	feet	8¾	inches (S).	North Atlantic					
Winter	12	feet	5	inches (W).	Allowance for fresh water for all freeboards	{	10	inches		

Witness my hand,

  
Secretary,

  
Chairman.

71, Fenchurch Street, London, E.C.3. 26th August, 1960.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register  
Foundation