

YESILIRMAK 3

Rpt C11 noted.

It is concluded the scantlings of
machinery casings and superstructures
are in accordance with approved plans.

LB
29/1/62

LD 8/2/62



© 2021

Lloyd's Register
Foundation

012875-012887-0236