

Ship's name M.H. THAMRIN

Port AMS.

No. 26365

Last survey date 14/10/64

Class is subject to

Repairs to cracked turbo blowers built-up
seatings being re-examined by 1.65 (12 mos)

C.S. Advanced.

It is submitted that this
vessel is eligible to remain
as **CLASSED**.

subject to above

MS

16 / 11 / 64



© 2021

Lloyd's Register
Foundation