

Copy of supplement to Vancouver letter of the
11th January, 1944, with First Entry Report on "FORT YUKON".

The following First Entry Hull Reports from Vancouver, B.C. should be modified so that under shell plating aft, on page 2, the bottom plating (four strakes) and bilge plating (one strake) read, in each case, .50" instead of .44".

<u>Shipbuilders.</u>	<u>Hull No.</u>	<u>Ship's Name</u>	<u>Rpt. No.</u>
Burrard Dry Dock Co. Ltd.	180	"Fort Columbia" ✓	5942
North Vancouver, B.C.	182	"Fort Bellingham" ✓	5954
	184	"Strathcona Park" ✓	5966
	186	"Fort St. Nicolas" ✓	5990
	188	"Fort Sakisdac" ✓	6006
	190	"Fort Machault" ✓	6023
	192	"Beaton Park" ✓	6046
 Burrard (Vancouver) Dry	181	"Fort Yukon" ✓	5950
Dock Co. Ltd.	183	"Wascana Park" ✓	5956
Vancouver, B.C.	185	"Fort Massac" ✓	5969
	187	"Fort Prudhomme" ✓	6002
	189	"Fort Venango" ✓	6018
	191	"Fort Orleans" ✓	6035 ✓
	193	"Fort St. Croix" ✓	6062
 North Van Ship Repairs Ltd.	127	"Fort Hall" ✓	5952
North Vancouver, B.C.	128	"Fort Clatsop" ✓	5955
	129	"Fort Colville" ✓	5970
	130	"Fort Pannure" ✓	6001
	131	"Fort Marin" ✓	6015
	132	"Fort Saleesh" ✓	6025
	133	"Dundurn Park" ✓	6045



© 2021

Lloyd's Register
Foundation

012966-012982-0286

Total

Gross Tonnage

Register Tonnage

REGISTERED

Length

Breadth

Depth

Lloyd's Register Foundation

©2021

Ship to be registered, name of the ship, and the name of the owner.

C.B. 'TEVNOCHNAV' most atropes Linn (vnae jarle gnivollo) 1881
'S' egged no 'tis gnitafq lleds rebnu jadt os bellibon eddluoda
(ekerts eno) gnitafq egld bus (ekerts twot) gnitafq metted eni
'Ab. to baetant "OG. eads dose ne pbaet"

ON .TGN	EMAY a'qlne	ON Linn	arebLnuqlne
2482	"alduoloo troq"	081	.Bdl .OD KOCQ YTD Bietne
4382	"adgnillab troq"	881	.C.B. 'tevnosneV deton
3382	"gnaf gnocltatst"	481	
0882	"alooit .js troq"	381	
3003	"adadlmas troq"	381	
2303	"llurodon troq"	081	
3403	"klsf notsae"	381	
0282	"nokuy troq"	181	YTD (TEVNOCHNAV) Bietne
3382	"krsf anasasw"	381	.Bdl .OD KOCQ
3382	"asasam troq"	381	.C.B. 'tevnosneV
3003	"amodbuq troq"	781	
8103	"ognanev troq"	381	
2303	"analeto troq"	181	
3303	"xloto.js troq"	381	
3382	"llah troq"	YSL .Bdl BrlaqeV qlne nav dtton	
3382	"gostalo troq"	881 .C.B. 'tevnosneV dtton	
0782	"allvloo troq"	081	
1003	"etunnaV troq"	081	
3103	"nlram troq"	131	
3303	"daseelas troq"	321	
3403	"krsf nruibnuq"	321	

No the master was the owner of the ship

2350 - 589574-235010

1.0.8

R 2

1 in

in the water

Side Keel

Middle Lin

Floors, Dep

SINGLE BOT

Bottom Foot

Are the scantin

and/or as ap

Panting Ar

Are the scant

State if Fram

Diameter and

" in Pea

" from 1

" Stem

" Decks

" Frames in U

Depth of Fram

Inter-

for Ice

Side FRAMIN

Frame Amid