

c Trawler Rules

Length (D 201 of Rules)\* 85.375 M

Breadth (D 202 of Rules) 13.500 M

Built at TAMISE, BELGIUM

Launched 1951

Yard No.



# LLOYD'S REGISTER OF SHIPPING

c/o Harrisons & Crosfield,

RECEIVED

Teromol Pos Dak. 715,

27 JUN 1960

Djakarta, Indonesia  
24 June 1960

Tel. 498 498, Djakarta

Reference  
JAB/EM

M.V. "TANDJUNG RAYA"

Djakarta Rpt. 5765

Dear Sir,

*noticed*

It is ~~noted~~ that in the Supplement No.12 to the Register Book this vessel has been assigned an Auxiliary Boiler Survey date of 7,59.

If you will kindly refer to Djakarta Report No .5633 you will note that the safety valves of this boiler have not been adjusted, the manhole door has been removed and placed in the Company's Store, with the resultant recommendation that the Boiler is not used until surveyed and its safety valves adjusted.

*lx and  
7/59.  
Subject to  
survey SKS*

It is noted that the M.V. "TANDJUNG TORAWITAN" has also been assigned an Auxiliary Boiler date of 7,59, in this case may I refer you to Djakarta Report 5660 which has similar recommendations.

*transf.  
7/59  
some  
subject*

The M.V. "TANDJUNG DATU" has not been assigned an Auxiliary Boiler Survey date in Supplement No.12.

*3/59.*


As the circumstances apertaining to these Auxiliary Boilers is the same for all the "TANDJUNG" vessels, to the effect that the Owner's do not intend using the Boilers - at least within the foreseeable future - it is suggested that a relevant notation be made in the SRL.A.

Yours faithfully,

*J.A. Boater*

J.A. Boater

The Secretary,  
LONDON



© 2021

Lloyd's Register  
Foundation

013008-013017-0032

013008-013017-0036 1/2

DJAK  
ESIA  
5660  
KART  
9  
ons,  
is  
he  
the  
on  
the  
the  
the  
the  
ng,  
ets,  
een  
ARCH  
e).  
le  
lon  
gister

500 to mile



© 2021

Lloyd's Register  
Foundation



e Trawler Rules  
Bre  
L