

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee London Telex
Telex No.: 24305

Telephone: ROYal 9166

31st July, 1959.

Dear Sirs,

Classn(S)

s.s. "PINNACLES"

I have your letter of the 27th July the contents of which have been noted, and I shall be glad if you can advance any reason for the internal pitting in the cargo tanks being now so bad as to warrant extensive wear and tear repairs to the bottom shell plating, bearing in mind that the ship carries the notation SS 7,56. (Dr.).

At the same time I have to say it is concluded that although the Special Survey is not due until July 1960, the repairs now recommended must, in your opinion, be dealt with before the ship is fit to continue as now classed.

Finally, I have to request that you will forward a list of the contemplated classification repairs now recommended for information and record purposes in this Office.

Yours faithfully,

Deputy Clerk to the
Classification Committee

The Surveyors,
BALTIMORE.

c.c. N.Yk.



© 2021

Lloyd's Register
Foundation

013033-013041-0098