

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, E.C. 3.

esn(S)
CFA

Dear Sir,

Steamer "PINNACLES"

With reference to Baltimore Report No. 9673, I shall be glad if you will ascertain from the Surveyors and let me know the number of crack arresters fitted in this vessel, as it would appear from the records in this Office that only two are fitted (port and starboard).

You will of course appreciate that this does not conform to the requirements of my recent Circular Letter regarding the reinforcement of T.2 Tankers.

Yours faithfully,

pro Clerk to the
Classification Committee.

Wm. Bennett, Esq.,
NEW YORK.



© 2021

Lloyd's Register
Foundation

013033-013041-0124