



Lloyd's Register of Shipping.

RECEIVED

13 FEB 1949

ANSD.....

95, Bothwell Street,

Glasgow, C.2. 17th February, 1949.

Dear Sir,

Steam Trawler "WAR WING".

Reference

S.

In reply to your letter of the 14th instant, I beg to acquaint you that the Surveyor reports that the above vessel carries the following equipment:-

Two stockless bower anchors - 1 @ 7 cwt. 2 qrs. 24 lbs. ✓
 and 1 @ 7 cwt. 2 qrs. 14 lbs. ✓

One stocked anchor - 2 cwt. 2 qrs. 8 lbs. Stock 2 qrs. 20 lbs. ✓

90 Fms. 1 inch dia. stud link cable. ✓

Hawsers and Warps: 60 fms. @ 6" and 60 fms. @ 4.1/2". ✓

From the above, the vessel's equipment is fully in accordance with the Rule requirements.

In Glasgow Report No. 73525 the mean diameter of chain cable was reported as being 29/32". This figure should be 1" diameter and the Surveyor regrets the error.

I am, Dear Sir,

Yours faithfully,

Norman Anderson
 Secretary to the
 Glasgow Committee.

The Secretary,
 LONDON.



© 2021

Lloyd's Register
 Foundation

013042-013051-0132

121

Referred to Mr. Perris.

RM
RM

24/2/49

ALL THE ...

... ..

... ..

... ..

... ..

... ..

... ..

© 2021

Lloyd's Register
Foundation

(MADE AND PRINTED IN ENGLAND.)
... ..

Special De...
Survey Pa...
this sur...
Gene...

Have the T...
Inner Botto...
Stringers...
Keelsons...
Floors...
Longitudina...
Transverse...
Reverse Fra...
Frames...
Beams & F...
Outside Plat...

Coaming...
Caulking of...
Decks...
PRESENT C...
Renew...
Remo...
Failed

SUMMARY

If so, is the Report sent now, or when will it be sent?

In damage...
offered

REPAIRS,
... ..

Last R