

COPY

LLOYD'S REGISTER OF SHIPPING

Djalan Raja Darmo No. 130, Sourabaya, Indonesia.

Sourabaya, 13th February 1958.

SHIP

Dear Sir,

All ships of Messrs. Djawatan Pelajaran Indonesia
Classed with the Society.

It has been learned from the Owners Representative at this Port that this gentleman received orders from his head office at Djakarta that from now on all ships belonging to the Indonesian Government have been taken out of class and that the services of the Society's Surveyors are not required any more on their ships which include the following ships classed with the Society :

| | | | | | |
|------|----------------|-----------|-----------------------|---|---|
| m.v. | BABUT | No. 02902 | in Reg. Book 1957/58. | | |
| " | BALAM | No. 02973 | " | " | " |
| " | BANGO | No. 03104 | " | " | " |
| " | BARAU | No. 03145 | " | " | " |
| " | BARLIAN | No. 03195 | " | " | " |
| " | BAJAN | No. 02961 | " | " | " |
| " | BEKAKA | No. 03425 | " | " | " |
| " | BENDALU | No. 03567 | " | " | " |
| " | BEO | No. 03650 | " | " | " |
| " | BETTET | No. 03793 | " | " | " |
| " | BIDO | No. 03853 | " | " | " |
| " | BIDURI | No. 03856 | " | " | " |
| " | BLEKOK | No. 04019 | " | " | " |
| " | BLIBIS | No. 04025 | " | " | " |
| " | BOGA | No. 04104 | " | " | " |
| " | BURDJANHAL | No. 04862 | " | " | " |
| " | DJADAJAT | No. 08129 | " | " | " |
| " | INTATA | No. 14500 | " | " | " |
| " | MANIKAM | No. 19391 | " | " | " |
| " | MENGKARA | No. 20451 | " | " | " |
| " | MUTIARA | No. 21493 | " | " | " |
| " | <u>PERMATA</u> | No. 24035 | " | " | " |
| " | PUSPARAGAM | No. 25093 | " | " | " |
| " | SAMUDERA | No. 27051 | " | " | " |
| " | INTAN | No. 14499 | " | " | " |

It has been advised to the Owners Representative at this Port to forward an official letter to Lloyd's Register of Shipping regarding the above mentioned subject.

Yours faithfully,

sgd. A. JACOBS.

The Secretary,
L O N D O N .



© 2021

Lloyd's Register
Foundation

013057-013062-0060