

31 OCT. 1922

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Motor Barge No. 1343

Rpt. Lon. No. 84393

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

It is submitted the Tampico Surveyor be informed that the question of the equipment of this vessel has been referred to the Owners Agents who have supplied certain information regarding the anchors and cables originally intended for the vessel and not for those actually placed on board. The Surveyor should be requested to make further enquiries with a view to obtaining particulars of the equipment now on board and to state whether the additional stiffening in way of the winch has now been fitted.

Lr. Tampico 31/10/22

30-10-22

9510-290310-150210

© 2021
Lloyd's Register
Foundation