

10m.11.20

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc. Motor Barge (1343) Rpt. Lon No. 84393.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Surveyors should be requested to state whether the stiffeners on bulkhead at frame 15, & ribs in butts of sheerstrake are spaced as required, & whether it is intended to supply a keedge anchor, which is required by the rules.

They should also state clearly what remains to be done at Tampico, & if possible give the address of the Owners.

dr. 23.6.21



© 2021

Lloyd's Register  
Foundation

013057-013062-0186