

Thickness

Range of tensile strength

Are the shell plates welded or flanged

Description

Boiler

Boiler No. M 314

Made by *Plenty Iron Ltd*

For *Messrs Rennie Forrest & Co*

Lon

Report No. *82811 83647*

It is submitted that the *Lon Spirit* Surveyors be
 requested to ascertain if this ~~boiler~~ *machinery* is intended for a
 vessel classed or intended for classification, and if so,
 when and at what port the ^{*is*} ~~boiler~~ is to be fitted on board.

Mr. C. Hill
Genl. Sps.



Date *1/1/20*

© 2021

Lloyd's Register
Foundation

2e.3.17.

10.10.20

013057 - 013062 - 0198