

by Chief Ship Surveyor *21/3/10* Received from Chief Ship Surveyor
NAME *Stl. Sc. Sg. "Consort"* Rpt. *Low.* No. *72465.*
Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

1st Entry. (Equipment)

It is submitted that, before this case receives the consideration of the Committee, the Hull Surveyors should be communicated with again and informed that the Survey for Classification has now been completed at Falmouth, with the exception of supplying 60 fathoms of chain cable of proper size, weight & test and they should be requested to learn from the Builders when this cable may be expected on board the vessel in order that arrangements may be made for examination of same and for verifying the test particulars with the Certificate of test.

*Lx. Vtl.
21/3/10.*



Lloyd's Register
Foundation
013103-013114-0285