

sta

22nd December, 1958.

GENOA

23752 "ESPERIA" - As recommended, except that the class has been continued without special condition in regard to the starboard chain cable swivel end piece. I acknowledge receipt of your letter of the 1st instant, the contents of which have been noted.

23783 "DUE GOLFI" - As recommended.

The proposal to postpone the Special Survey until October, 1959 has been approved by the Committee and I shall be glad if you will inform the Owners accordingly.

I shall be glad if you will let me know what definite and early arrangements the Owners propose to make to complete the Donkey Boiler Survey.

23789 "GIULIO CESARE" - As recommended except that the notation of DMS 9,58 has not been assigned as according to the records

© 2021

Lloyd's Register
Foundation

cont'd...

013161-013167-0058 1/2

22nd December, 1958.

where the exhaust gas economiser remains to be examined and its safety valves adjusted. You should make arrangements with the Owners for this to be done.

"CRISTOFORO COLOMBO"

3662, 23705, 23758/ - As recommended except that it is considered, in view of the fact that the repairs were not carried out to the fractured floor web, that this item should be regarded as a condition of class, and you should therefore issue an amended Interim Certificate incorporating the recommendation that fractured floor web No. 5 from aft, starboard side, in No. 25 double bottom tank should be permanently repaired by completion of the Special Survey.



© 2021

Lloyd's Register
Foundation

0058 2/2