

14 FEB 1958

Received from Chief Ship Surveyor.....

SHIP'S NAME "MARE ADRIACUM" REPORT Gen. No. 22976

GB

Outstanding Conditions of Class:

Subject to indented side shell plate (p.s. amid) being dealt with by next Special Survey and to the rudder being specially examined and dealt with as necessary at next drydocking.

Endorsement of Certificate (As before ~~xxx None xxx~~)

Surveys due: SPECIAL SURVEY (A) due 3,58.

Nature of Present Survey: (Afloat and in dry dock)

Special Survey: Damage repairs including subject items: Alterations and reinforcement of shell plating.

Special Features:

Is Interim Certificate in order (Yes ~~xxx None xxx~~)

Items Outstanding: (If any for S.S.)

NONE.

S.S. ~~xxxxx~~ completed by xxx

Recommendation:

SUBMITTED record of 'DS 12,57' and Notation of 'SS Gen. 12,57' be assigned, without special conditions but with Endorsement of Certificate.

DS 12,57  
SS Gen. 12,57 Without.

ENDORSEMENT OF CERTIFICATE  
Indents in poop side plating (s.s.).

IN L.O.E.  
(Main structure partly of P.403 Steel).

FREEBOARD SURVEYORS TO NOTE this report.

MR G. BUCHANAN.

Blk (new)

It is considered the Surveyors might be complimented on the manner in which the details of repairs have been recorded in this case.

NOTED  
O.S.S.  
RECORDS  
DEPT.

© 2021  
Register  
Foundation  
4/2/50

7600-161310-981310