

Received from Chief Ship Surveyor

28 JUL 1958

SHIP'S NAME

"HIKAWA MARU".

REPORT s

(Kob. (A)

5836

(Yka. (B)

No. 2635.

W

Outstanding Conditions of Class: SUBJECT TO slightly waved Nos. 1 & 2 keel plates, from forward, being specially examined and dealt with as necessary next drydocking.

Endorsement of Certificate (~~As before~~ None)

Signature of Present Survey: (Afloat and in dry dock)

- (A) Repairs on account of 3 damages, wear and tear repairs and alterations.
- (B) Testing of heating coils in ^{deep tanks in} No. 3 hold (p & s).

Recommendation:

SUBMITTED record of DS 6,58 subject as above.

DS 6,58 Subject.

C.S.S. Records Dept.
to note.

S.R.L. APPENDIX.

(main structure partly of P.403 Steel).

SUBMITTED also the Surveyors be requested to advise the reason for the ~~reinforcing~~ reinforcing of the shell plating in way of No. 1 D.B. tank and confirm that the slightly waved Nos. 1 & 2 keel plates from forward, previously noted as a condition of Class as a result of a Survey held at Kobe 4, 56, refer Kobe report No. 4583, have now been dealt with.

Blk(new)

013201-013210-0112

See letter 11.8.58

© 2021

Lloyd's Register Foundation

22
2
58