

COPY

Ship's name

"LUBEN KARAVELOV"

Port

RR

No. 61

Last survey date

Class is subject to

NONE.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and ~~in~~ drydock)

Damage (contact) involving side shell plating in way of
frs.131/134 etc. (s.s) - temporary repairs.

Recommendation

SUBJECT to indented side shell plating
etc. in way of frs.131/134 (s.s) being
specially examined and dealt with
as necessary next drydocking.

As Now. Subject



© 2021

Lloyd's Register
Foundation

013224-013231-0010