

013240-013244-0194

0m.1,37.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME "ASAKA MARU" Rpt. Kob. No. 10475
Yka. 6304

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Kobe Surveyors report this vessel examined afloat and on account of damage through collision, 3 stern plates renewed, 7 shell plates repaired, repairs to deck, framing and minor repairs effected.

The Yokohama Surveyors report a bower anchor and 2 lengths of chain cable supplied to replace lost equipment.

It is submitted the vessel appears worthy to remain as classed without record of survey.

The Yokohama Surveyors should be requested to forward the usual particulars of the test of the anchor and the weight and test of the chain cable supplied also makers of cables