

16 DEC 1965

HQ 3266

SHIP'S NAME

MONSUN

PORT

No.

LAST SURVEY DATE

CLASS IS SUBJECT TO

1. Repairs to welds of stiffening plates between m.e. 'A' frames Nos 829 fwd 2 ft and No. 6 aft postside (LW 669) being specially examined by 6.66 (12 mos).
2. P. Fwd end of m.e. 'A' frame plating at centre of engine in way of chain drive casing repair (9.65) being examined by 3.66

ABS commenced 9.65 complete.

It is submitted that this
vessel is eligible for THE
RECORD. ABS 9.65

subject to above

ag

15/12/65



© 2021

Lloyd's Register
Foundation