

~~XXXX~~

18 NOV 1965

SL Ship's name "MADELEINE" Port H.KG No. 19640

Last survey date 11.9.65

Class is subject to indented shell plates G.8,9 & 10 (s.s.from aft) being specially examined and dealt with as necessary next drydocking.

ACTION is DEFERRED for completion of the S.S. by 6,65.

S.R.L. Appendix (as before ~~XXXXXX~~)

Surveys due

SPECIAL SURVEY (C) due 12,64 - commenced Ham 12,64. Postponement of completion of the S.S. until 6,65 approved 11.8.64 following a satisfactory G.E.. Request for further postponement until 10,65 approved 7.5.65.

Nature of present survey (afloat and in drydock)

Docking: Completion of the S.S.
Permanent repairs to damage (collision and unknown) including deferred items as above.

Is interim certificate in order Yes/No/None

Items outstanding if any for SS

NONE

SS proposed to be completed by

Recommendation SUBMITTED record of DS 8,65 and Notation (DR 4 years) 9,65 be assigned, without special conditions.

DS 8,65
SS (DR 4 years) 9,65. Without.

IN S.R.L. APPENDIX
(Main structure partly of P.403 Steel).



© 2021

CERTIFICATE WRITTEN.

Lloyd's Register
Foundation