


COPY

# LLOYD'S REGISTER OF SHIPPING



Port of Piraeus,

5th December, 1962.

**This is to Certify** *that I have surveyed part of the machinery of the S.S. "ESSO JAMAICA" of Panama, Gross tons 23457 for Docking Survey, Continuous Survey of Machinery & Main Boiler Survey, whilst the vessel lay afloat & in drydock at Skaramanga on the 22nd November, 1962, & subsequently,*

*and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned M.B.S. 12,62 & C.S. (with date) now.*

Parts now examined:—

(For C.S.)

L.P. Main Turbine, casings, rotors, blading, bearings & thrusts.  
Thrust blocks, shafts and bearings.  
Intermediate shafts and bearings.  
Holding down bolts and chocks.  
Stop and manoeuvring valves.  
Transfer pump, Stbd. main extraction pump, ballast pump,  
General Service pump, Aft Oil Fuel pump.  
Feed heater (2nd & 3rd stages).  
Upper Oil Fuel heater.  
Fire extinguishing arrangements.  
Auxiliary engine (emergency).  
Air ejectors.  
Distillers.  
Main engine tested under working conditions.

*G. T. Meikle*

G.T.Meikle.

Surveyor to Lloyd's Register of Shipping

ABS Auxiliary Boiler Survey  
CSM Continuous Survey of Machinery  
DBS Donkey Boiler Survey  
ES Engine Special Survey

MBS Main Boiler Survey  
OF Fitted for oil fuel (date) FP above 150°F.  
SGS Steam Generator Survey  
SPS Steampipe Survey

KEY TO ABBREVIATIONS

TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."