

COPY

KOBÉ

11431

Ship's name

LUGANSK

Port

PIRAEUS

No.

10153

Last survey date

Class is subject to

N.L.

Before this case receives consideration it is concluded that the secondary safety valves of the auxiliary boilers were also adjusted under steam, but this should be confirmed by the Piræus Surveyors.

It will also be noted that the exhaust gas economiser safety valves have to be adjusted under steam & complete the boiler survey with date of ABS 2.63.

Amended intermediate certificate to be issued accordingly 1-20 2/5/63.

013322-013328-0173

© 2021
Lloyd's Register
Foundation