

NAB

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

20th February 1962.

Dear Sirs,

S.S. "EMPIRE LUCY"

I have your letter of the 15th February, the contents of which have been noted, and would inform you that the survey position is as follows:-

Special Survey due 10.62
Boiler Survey due 11.61
Screwshaft Survey due 9.61
Steampipe Survey due 11.66
Ship last seen in drydock 11.60.

There are no conditions of class noted against this vessel.

From the above it will be noted that the Screwshaft and Boiler Surveys are overdue and the new Owners' intentions regarding these inspections are awaited.

Yours faithfully,

Clerk to the
Classification Committee.

The Surveyors,
GENOA



© 2021

Lloyd's Register
Foundation

013339-013345-0176