

5th March, 1962.

two

HONG KONG

16658, 73A, 76, 79, 86 - As recommended.

"WESTWIND" 16694 - As recommended.

16718 "NIVANGA" - As recommended, except that assignment of class has been deferred pending receipt of information from the Owners that the ship has arrived in a satisfactory condition within the service area.

With reference to the Secretary's letter dated 9.6.61 Ref. "Eng." I shall be glad to receive your comments regarding gear hammer during trials.

16724 "TEH HU" - As recommended, postponement of the Special Survey until December, 1962 having been approved, and I shall be glad if you will advise the Owners accordingly.

I would point out that the examination of all parts of the boiler for the Boiler Survey should be stated in the appropriate space in the report in all future similar cases.

16755 "BRENDA" - As recommended, except that the class has been continued subject also as previously recorded.

16757 "LEXA MAERSK" - As recommended, except that assignment of the notation SS 1,62 has been deferred as according to the records in this office Nos. 7 and 8 deep tanks (tunnel wing tanks) require to be tested for completion of the Special Survey.



Lloyd's Register  
Foundation

013376-013382-0113