



Reference

R.
NAB/BJS.

LLOYD'S REGISTER OF SHIPPING

Telephone: West Hartlepool 2432

47, Church Street, West Hartlepool
5th November, 1962.

RECEIVED

6 - NOV 1962

Ans'd

Dear Sir,

s.s. "EVANDROS"

We are in receipt of your letter of the 2nd instant regarding the above vessel.

In reply we have to state that the Owners have not been able to complete the Main Boiler Survey by having the starboard boiler surveyed at this port owing to lack of time. They state that this boiler will be surveyed when the ship reaches Italy to which country it is proceeding direct.

Yours faithfully,
The Surveyors,
per:-

The Secretary,
LONDON.

013390 - 013396 - 0067



Lloyd's Register
Foundation

1/5 + 1/6 = 2 1/6

proceeding direct.
The ship rescues itself to water contrary to the
They state that this boiler will be an
announced at this point owing to lack of
boiler survey of heating the standard point.
Others have not been able to complete the work
in light we have to state that the

U.S. PATENT OFFICE

© 2021

Lloyd's Register
Foundation