

MEMORANDUM**From : LLOYD'S REGISTER OF SHIPPING,**71, FENCHURCH STREET,
LONDON, E.C.3.R
(Ref. H.)**To :** The Surveyor(s) at SYDNEY, N.S.W.

Date: 10th October 1961.

Vessel's Name: S.S. "KARUAH"

24 OCT 1961

Amal Rpi.

QUESTION

ANSWER

Date:— 17th October, 1961.


With reference to my letter of the 1st June, I shall be glad to learn how this case stands as regards the requisite General Examination.

I would draw your attention to the entry in the S.R.L. and conclude that the condition of class will be dealt with at the General Examination.

The high main circulating inlet valve chest also requires to be renewed at the next dry docking.

The vessel was submitted for General Examination afloat and in dry dock during the present week when the SRL Items and Propeller Shaft survey were dealt with.

Our Report will follow in due course.




© 2021

Lloyd's Register
Foundation

16 OCT 1961

013390 - 013396 - 0229