

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME "IMPERIAL EDMONTON" REPORT Bal. No. 11276.
 JD.

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Nature of Survey Docking. Equipment. When due.....

NOTED

SUBJECT to 30 fathoms of chain cable being replaced by cable in accordance with Rule requirements at the earliest opportunity.

OFFICE NOTE:

Structural reinforcement fitted - S.Fo. 11,52(T2T).
 Docking brackets fitted Vcr. 10,53.

ENDORSEMENT OF CERTIFICATE.

Sheerstrake plating (p.s.amids.) slightly set in.
 Welded seam between 'A' & 'B' strakes (p & s.amids.) slightly set in.



© 2021

Lloyd's Register
 Foundation

013397-013402-0028

CRAM
 4-2-58