

M/M.13410

Lloyd's Register of Shipping

231 St. James Street West,

Montreal 1.

23rd August, 1946



RECEIVED
7 - SEP 1946
X R J
ANSD.....

The Secretary
LONDON

Dear Sir;-

Montreal Report No. 6655

"SAULT-AU-MOUTON"

We are in receipt of the Classing Letter dated the 26th ultimo, and in accordance with instructions contained therein, the Owners of the M/V "SAULT-AU-MOUTON" have been duly advised that, owing to the omission of the bottom cement, the bottom will require to be examined internally annually. ✓

With regard to the testing of the steering chains, we herewith enclose copy of the Test Certificate for these Chains, which we trust will be found satisfactory. ✓

Yours very truly,

W. Hobson

Enclosure
ND:FC

Principal Surveyor in Canada



© 2021

Lloyd's Register
Foundation

013409-013416-0059

AR

^m/ Referred to Mr. Perris

P26

Key



© 2021

Lloyd's Register
Foundation