

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

TELEPHONE : 36873 (2 LINES)

2nd  
dk)

RECEIVED  
**Lloyd's Register of Shipping,**

Ocean Chambers, Lowgate,  
Hull, 7th December, 1946.

Reference

S. \_\_\_\_\_

Dear Sir,

ANSD  
9 DEC 1946  
\*\*\*\*\*

With reference to your classing letter of the 29th November regarding the "GREBBESTROOM", our report No. 53793, we enclose herewith two test certificates for dynamos and one motor test certificate. The rest will follow as soon as received.

We are, Dear Sir,  
Yours faithfully,  
The Surveyors,  
Per:-

The Secretary,  
LONDON.



182221  
*W. H. Cornell*

Lloyd's Register  
Foundation

013588-013595-0007

Vertical stamp: 182221

~~Referred to Mr. Carr~~

*22/12/1946*

*R. J. Carr*

For Engineer Superintendent  
The Admiralty,  
Whitehall, London S.W. 1.

Dear Sir (Rate),  
The enclosed herewith are two test certificates for the "CHRYSEALUMINA" and "LORON" with reference to your enclosing letter of the 23rd

*Notes to await further call*  
*TRM*

LONDON.  
The Secretary.

of the test as soon as received.  
The enclosed herewith are two test certificates for the "CHRYSEALUMINA" and "LORON" with reference to your enclosing letter of the 23rd

10/11/46 Dec 1946

Office of the Secretary

Department of the Admiralty



Lloyd's Register Foundation

extr...  
book...  
raser...  
free...  
de c...  
ules...  
fram...  
nd...  
st...  
D

The ren