



LLOYD'S REGISTER OF SHIPPING

Fondé en 1760. Réorganisé en 1834.

RÉUNI AVEC LE BRITISH CORPORATION REGISTER

RECONNU PAR LA LOI SUR LA SÉCURITÉ DE LA NAVIGATION MARITIME

(ARRÊTÉ MINISTÉRIEL DU 5 SEPTEMBRE 1908)

Tél. FRanklin 12-56 1, Rue Ferrandière, Lyons (2 me)

Téléphone: Franklin 89.58 65.90 65.91 65.92

RECEIVED 9th March, 1957.

11 MAR 57

Am'd

Dear Sir,

Chantiers de l'Atlantique, yard N° B.17
2. Turbo-Alternators 650 KW, Forges & Ateliers
du Creusot.

We beg to draw your attention to an error in our
First Entry Report N° LYO E.11 covering the above mentioned
Turbo-Alternators. The serial numbers of the turbines and
alternators should be as follows:

| | | |
|----------------|---------|---------------------------|
| Turbine N° 238 | driving | alternator N° <u>9186</u> |
| | | (and not N° 9816) |
| " " 239 | " | alternator N° <u>9185</u> |
| | | (and not N° 9815). |

It would be appreciated if you would amend our
report accordingly and we regret any inconvenience this may
have caused.

Yours faithfully,

The Surveyors.

per:

Kbmm

The Secretary,
London

cc.: Nantes



© 2021

Lloyd's Register
Foundation

013588 013595 0184

10/10/10

bioRxiv preprint doi: <https://doi.org/10.1101/000000>; this version posted January 1, 2016. The copyright holder for this preprint (which was not certified by peer review) is the author/funder, who has granted bioRxiv a license to display the preprint in perpetuity. It is made available under aCC-BY-NC-ND 4.0 International license.

THE PATENT OFFICE

YOUNG LESTER

THE CHURCH
OF THE HOLY SPIRIT

[illegible]

Dear Sir,

© 2021

Lloyd's Register
Foundation

TONNAGE and Deck

~~State~~ Type (1)