

Ship's name

"PETER LEIGH"

Port

Liv.

No. 163394

GB

Class is subject to set up bottom plating forward also wasted
after keel plate being specially examined and dealt
with as necessary next drydocking.

Last survey date 9.1.64

S.R.L. Appendix (as before ~~on xxxxxx~~)

Nature of present survey (~~xxxxxx~~ in drydock)

Docking: Permanent repairs to H.W. damage:
Examination of S.R.L. and S.R.L. Appendix items.

~~Recommendation~~

N O T E D

DS 1,64 Subject as above.

DS 1,64 Subject

IN S.R.L. APPENDIX.

(~~Bottom~~ plating hogged)

C.S.S. Records Dept.
to note.



Lloyd's Register
Foundation

8/1/64
27-2-64
4