

Ship's Name SS/MS "PETER LEIGH" Gross tons 320
 Is there a rpt. 8? *yes* Port Liverpool Rpt. No. 163394
 No. of visits 2 First date 7.1.64. Last date 8.1.64.
 Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only)
 Date of completing rpt. 31.1.64. Surveyed at, if different from Port above
 Is a rpt. 9A attached? No MN Nature of survey Docking
 Survey fees Damage fee Expenses
Null ✓ *fo* ✓ S.A. fee ✓

DOCKING
 Propeller Good Sea connections Not exam'd Oil gland -
 Fastenings Good Wear down of stern bush Not taken
 Has screw/tube shaft been drawn? No Date of examn. -
 Has shaft been changed? - Has shaft now fitted been previously used? -
 Has shaft now examined/fitted a continuous liner? - Approved oil gland? -

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG)	MAIN
Air heaters	
Superheaters	
Safety valves	
Mountings, doors and fastenings	
Safety valves adjusted to { Sat / Spt	
Boiler securing arrangements	
Main economisers	Exhaust gas heated economisers
Steam heated steam generators	Steam generator safety valves adjusted to
Forced circulating pumps	Funnel
Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?	Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed ~~with~~ without fresh record ~~if~~ subject to any outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee LIVERPOOL 18 FEB 1964 F.E. Higgins.
 Minute *As now subject* Surveyor to Lloyd's Register of Shipping

ALSO FOR
SPL FOR
TRO
SRL ✓
POSTING
HEADER
CERT

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before the date a distinguishing mark thus should be entered against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

013639 - 013642 - 0171

