

COPY

Ship's name "PETER BEIGH"Port BRSNo. 2152Last survey date 16.10.62.Class is subject to

set up bottom plating forward being
specially examined and dealt with as
necessary at the next drydocking.

S.R.L. Appendix (as before or none)Nature of present survey (afloat and in drydock)Docking:

Wear and tear repairs.

Examination of S.R.L. & S.R.L. Appendix items.

Recommendation

SUBMITTED record of DS 10,62 be assigned,
subject as above.

DS 10,62 Subject.

IN S.R.L. APPENDIX.

Bottom plating hogged.

End. S.1

be retained, imposed, amended or deleted, particulars
must be stated above and on the interim certificate.)



© 2021

Lloyd's Register
Foundation

N. X. Neilson
Surveyor to Lloyd's Register of Shipping

SRL