


COPY 8 No. 13334
Kobe Rpt.

LLOYD'S REGISTER OF SHIPPING

B-106990



Port KOBE

Date 14th September, 1964.

This is to Certify that I have surveyed the **s.s. "DAIKYO MAMU"** **13,224** Gross tons of Tokyo whilst she lay afloat and in drydock at Aioi, Japan on the 26th August, 1964 and subsequently for Docking and Commencement of Special Survey "C" due 8,65

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she ~~be~~ remain as classed with fresh record of drydocking 8,64 and with the notation of SS (with date) on completion.

Now done for Special Survey.

Examined Internally:

Double Bottom Tanks: No.2 Feed Water.
No.4 Feed Water.

Oil Fuel Settling Tank: No.2
Oil Fuel Bunker Tanks: No.2
No.3
No.5

Pressure-tested:

Oil Fuel Settling Tank: No.1.
Oil Fuel Bunker Tanks: No.1 (excepting forward transverse bulkhead and centre-line bulkhead).
No.4 (excepting forward transverse bulkhead).

To complete Special Survey:

All other items not stated above.

A.S. Scott
Surveyor to Lloyd's Register of Shipping
A.S. Scott

KEY TO ABBREVIATIONS

| | | | |
|----|--|--------|----------------------------------|
| AS | Annual Survey | SS | Hull Special Survey |
| BS | Biennial Survey | SS(Dr) | Hull Special Survey (Drilling) |
| DS | Docking Survey | SS(M) | Hull Special Survey (Modified) |
| NS | Cargo Battens not fitted (No Sparring) | SSH | Hull Special Survey (Continuous) |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B) 5,64 KOE

© 2021 Lloyd's Register Foundation
013639 - 013642 - 0208