

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1760

RE-CONSTITUTED 1834

Certificate of Class

Steel Screw Steamer "DAIKYO MARU"
Official Number 70867 Port of Registry Yokkaichi
Owners Daikyo Sekiyu K.K.
Builders, and where and when built Harima Zosenso K.K., Aioi, August, 1953.

REGISTERED PARTICULARS

Length	553.68 feet	Tonnage, Gross	13224.20
Breadth	73.16 feet	Ditto under Deck	-
Depth	40.35 feet	Ditto Net	9553.47


This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 29th August, 1953 in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character  100A1 Carrying Petroleum in Bulk. Fitted for oil fuel 8,53 flash point above 150°F. subject to Periodical Surveys as required by the Rules.

The approved minimum freeboards from the deck line are as follows:—

Tropical	2616 feet mm. inches (T).	Winter North Atlantic	3151 feet mm. inches (WNA).
Summer	2814 feet mm. inches (S).	Allowance for fresh water for all freeboards	213 mm. inches
Winter	3012 feet mm. inches (W).		

Witness my hand,


Secretary,


Chairman.


71, Fenchurch Street, London, E.C.3.

15th January, 1954.

N.B. If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation

1007